## **WEST Search History**

Hide Items Restore Clear Cancel

DATE: Sunday, December 24, 2006

Hide?	<u>Set</u> Name	Query	Hit Count
DB=PGPB, USPT; PLUR=YES; OP=OR			
	L17	L16 and @pd > 20060623	5
<u>;</u>	L16	L12 or L11	75
	L15	L13 and L9	0
П	L14	(steel and (normalize or normalized or normalizing) and creep and ("coarse carbide" or "creep damage" or haz or "heat affected zone")).clm.	0
П	L13	L12 not L11	53
Π	L12	(steel and (normalize or normalized or normalizing) and creep and ("coarse carbide" or "creep damage" or haz or "heat affected zone"))	57
	L11	(steel and (normalize or normalized or normalizing) and creep and ("type 4" or "type IV"))	22
	L10	(steel and (normalize or normalized or normalizing) and creep and ("type 4" or "type IV")).clm.	0
<b></b> !	L9	(428/681 or 428/682 or 428/683 or 148/516 or 148/519 or 148/521 or 148/529 or 228/262.41)![CCLS]	1736
DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR			
Г	L8	("type 4" or "type IV") and creep and steel and (normalize or normalized or normalizing)	0
	L7	L6 or L4	35
	L6	L5 not L4	28
	L5	steel and (normalize or normalizing) and (haz or "heat affected zone")	29
$\Box$	L4	L2 or L1	7
	L3	L2 not L1	5
	L2	steel and (haz or "heat affected zone") and ("coarse carbide" or "creep damage")	6
	L1	steel and (normalize or normalizing) and ("coarse carbide" or "creep damage")	2

**END OF SEARCH HISTORY**